
DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 1.28

WELDING INSPECTION REPORT

Resident Engineer: Casey, William **Report No:** WIR-029767 Address: 333 Burma Road **Date Inspected:** 23-Jun-2013

City: Oakland, CA 94607

Project Name: SAS Superstructure **OSM Arrival Time:** 700 **OSM Departure Time:** 1530 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: American Bridge/Fluor Enterprises, a JV **Location:** Job Site

CWI Name: CWI Present: Yes No As noted below **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No

N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A **Qualified Welders:** Yes No N/A **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:**

> Yes **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** SAS

Summary of Items Observed:

Quality Assurance Inspector (QA) Douglas Frey was at the American Bridge/Fluor (ABF) job site at Yerba Buena Island in California between the times noted above in order to monitor Quality Control functions and the in process work being performed by ABF personnel. The following items were observed:

This QA Inspector randomly observed ABF/JV welder Donald Plumb #0891 perform Shielded Metal Arc Welding (SMAW) on the Partial Joint Penetration (PJP) joints of the E2/E3 WB Traveler handrails. The welder was observed utilizing WPS ABF-D1.5-1160 for PJP welding. The welder was observed preheating the surface area prior to welding and other welding parameters as inspected by the QC Inspector were recorded as 128 amperes and appeared to be in compliance with the WPS noted above. The QA Inspector made subsequent observations throughout the shift to monitor quality and noted that the work was completed on this date and appeared to be in general conformance with the contract documents. RFI-003309ROO was referenced during the observations.

This QA Inspector reported to crossbeam 8 to monitor and observe operations to return the damaged area to service. The QAI observed ABF personnel utilizing 8 barrel jacks with through rods to the exterior of the crossbeam to further straighten the section. The QAI made subsequent observations throughout the shift and noted that the work is in progress. ABF-SUB-002845R00 was referenced during this observation.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

N/A

N/A

No

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Conversations on this date were relevant to work performed.





Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Gary Thomas 916-764-6027, who represents the Office of Structural Materials for your project.

Inspected By:	Frey,Doug	Quality Assurance Inspector
Reviewed By:	Reyes,Danny	QA Reviewer